

<b>AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT</b>				1. CONTRACT ID CODE		PAGE OF PAGES 1   18	
2. AMENDMENT/MODIFICATION NO. <b>P00001</b>		3. EFFECTIVE DATE <b>13-Mar-2018</b>		4. REQUISITION/PURCHASE REQ. NO. SEE SCHEDULE		5. PROJECT NO.(If applicable)	
6. ISSUED BY CODE <b>N00164</b>  NAVAL SURFACE WARFARE CENTER CRANE DIV (b)(6) BLDG 121 300 HIGHWAY 361 CRANE IN 47522-5001		7. ADMINISTERED BY (If other than item 6) CODE <b>S3605A</b>  DCMA DAYTON BUILDING 30 AREA A 1725 VAN PATTON DRIVE WRIGHT-PATTERSON AFB OH 45433-5302					
8. NAME AND ADDRESS OF CONTRACTOR (No., Street, County, State and Zip Code) TRI STAR ENGINEERING, INC. (b)(6) 3000 W 16TH ST BEDFORD IN 47421-3332				9A. AMENDMENT OF SOLICITATION NO.			
				9B. DATED (SEE ITEM 11)			
				X 10A. MOD. OF CONTRACT/ORDER NO. <b>N0016417FW073</b>			
				X 10B. DATED (SEE ITEM 13) <b>12-Jul-2017</b>			
CODE <b>03WZ3</b>		FACILITY CODE					
11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS							
<input type="checkbox"/> The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offer <input type="checkbox"/> is extended, <input type="checkbox"/> is not extended. Offer must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended by one of the following methods: (a) By completing Items 8 and 15, and returning _____ copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.							
12. ACCOUNTING AND APPROPRIATION DATA (If required)							
13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS. IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.							
A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.							
B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103(B).							
X C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: <b>FAR 43.103(a)(3)</b>							
D. OTHER (Specify type of modification and authority)							
E. IMPORTANT: Contractor <input type="checkbox"/> is not, <input checked="" type="checkbox"/> is required to sign this document and return <u>1</u> copies to the issuing office.							
14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.) Modification Control Number: <b>pdr70318770</b> The purpose of this modification is to: 1) incorporate Request for Variance (RFV) Number TSE-001 for AN/SPS-49 Pedestal serial number (S/N) 49P-09 (E-21) - See Attachment 3 in section J. 2) update delivery schedule and ship to address. 3) authorize Category 2 and Category 3 levels of repair of AN/SPS-48 Antenna, S/N 48A-04 (D39). 4) authorize Category 2 and Category 3 levels of repair of AN/SPS-48 Pedestal, S/N 48P-04 (D39). 5) update the serial number information. 6) update the SGFP form to include the revised serial number information. 7) update Attachment 2 - Planned Induction Schedule. All other terms and conditions remain unchanged.							
Except as provided herein, all terms and conditions of the document referenced in Item 9A or 10A, as heretofore changed, remains unchanged and in full force and effect.							
15A. NAME AND TITLE OF SIGNER (Type or print)				16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print)			
				(b)(6) CONTRACTING OFFICER			
				TEL: (b)(6)		EMAIL: (b)(6)	
15B. CONTRACTOR/OFFEROR		15C. DATE SIGNED		16B. UNITED STATES OF AMERICA		16C. DATE SIGNED	
				(b)(6)			
(Signature of person authorized to sign)				(Signature of Contracting Officer)		13-Mar-2018	

SECTION SF 30 BLOCK 14 CONTINUATION PAGE

**The following items are applicable to this modification:**

**SUMMARY OF CHANGES**  
**SUMMARY OF CHANGES**

SECTION B - SUPPLIES OR SERVICES AND PRICES

SUBCLIN 0001AA

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-48 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.2). Serial Number (S/N): 48A-03

To:

Teardown and evaluation of USN assets for the AN/SPS-48 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.2). Serial Number (S/N): 48A-03 (C32).

SUBCLIN 0001AB

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-48 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.2). S/N: 48A-04

To:

Teardown and evaluation of USN assets for the AN/SPS-48 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.2). S/N: 48A-04 (D39).

SUBCLIN 0002AA

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-48 Pedestal in accordance with

Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.1). S/N: 48P-03

To:

Teardown and evaluation of USN assets for the AN/SPS-48 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.1). S/N: 48P-03 (C-25).

SUBCLIN 0002AB

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-48 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.1). S/N: 48P-04

To:

Teardown and evaluation of USN assets for the AN/SPS-48 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.6 and subparagraphs and Appendix A Parts and Inspection Supplement (thru section 5.1). S/N: 48P-04 (D39).

SUBCLIN 0003AA

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-49 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 4.2). S/N's: 49A-06, 49A-07, and 49A-08

To:

Teardown and evaluation of USN assets for the AN/SPS-49 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 4.2). S/N's: 49A-06 (F-20), 49A-07 (CR001), and 49A-08 (K0).

SUBCLIN 0003AB

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-49 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 4.2). S/N: 49A-09

To:

Teardown and evaluation of USN assets for the AN/SPS-49 Antenna in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 4.2). S/N: 49A-09 (K-15).

SUBCLIN 0004AA

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-49 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 5.1). S/N's: 49P-06, 49P-08, and 49P-09

To:

Teardown and evaluation of USN assets for the AN/SPS-49 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 5.1). S/N's: 49P-06 (B-8), 49P-08 (G1), and 49P-09 (E-21).

SUBCLIN 0004AB

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-49 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 5.1). S/N: 49P-10

To:

Teardown and evaluation of USN assets for the AN/SPS-49 Pedestal in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.7 and subparagraphs and Appendix B Parts and Inspection Supplement (thru section 5.1). S/N: 49P-10 (P-25).

#### CLIN 0005

The CLIN extended description has changed from:

Teardown and evaluation of USN assets for the AN/SPS-67(V)1 Antenna system in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.9 and subparagraphs and Appendix D Parts and Inspection Supplement (thru section 5.1). S/N's: 67S-05 and 67S-06  
See Price Matrix for CLIN 0005 Below Minimum 1 Maximum 60

To:

Teardown and evaluation of USN assets for the AN/SPS-67(V)1 Antenna system in accordance with Statement of Work paragraphs 3.1 thru 3.6.5 and 3.6.9 and subparagraphs and Appendix D Parts and Inspection Supplement (thru section 5.1). S/N's: 67S-05 (180) and 67S-06 (J25)  
See Price Matrix for CLIN 0005 Below Minimum 1 Maximum 60.

#### SUBCLIN 0007AA

The CLIN extended description has changed from:

AN/SPS-48 Antenna Category 1 Repair(Contractor Site)Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and subparagraphs. S/N: 48A-03

To:

AN/SPS-48 Antenna Category 1 Repair(Contractor Site)Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and subparagraphs. S/N: 48A-03 (C32).

#### SUBCLIN 0007AB

The CLIN extended description has changed from:

AN/SPS-48 Antenna Category 1 Repair (Government Site) in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and specifically subparagraph 3.6.6.8. S/N: 48A-03

To:

AN/SPS-48 Antenna Category 1 Repair (Government Site) in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and specifically subparagraph 3.6.6.8. S/N: 48A-03 (C32).

SUBCLIN 0007AC

The CLIN extended description has changed from:

AN/SPS-48 Antenna Category 1 Repair(Contractor Site)Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and subparagraphs. Note: This is in accordance with SLIN 0007AA on basic contract. S/N: 48A-04

To:

AN/SPS-48 Antenna Category 1 Repair(Contractor Site)Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and subparagraphs. Note: This is in accordance with SLIN 0007AA on basic contract. S/N: 48A-04 (D39).

SUBCLIN 0007AD

The CLIN extended description has changed from:

AN/SPS-48 Antenna Category 1 Repair (Government Site) in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and specifically subparagraph 3.6.6.8.Note: This is in accordance with SLIN 0007AB on basic contract. S/N: 48A-04

To:

AN/SPS-48 Antenna Category 1 Repair (Government Site) in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.6 and specifically subparagraph 3.6.6.8.Note: This is in accordance with SLIN 0007AB on basic contract. S/N: 48A-04 (D39).

SUBCLIN 0008AA

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Pedestal in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1, 3.6.6 and subparagraphs including labor for subassemblies in the SPS-48E appendix A under Cat 1. S/N: 48P-03

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Pedestal in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1, 3.6.6 and subparagraphs including labor for subassemblies in the SPS-48E appendix A under Cat 1. S/N: 48P-03 (C-25).

SUBCLIN 0008AB

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Pedestal in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1, 3.6.6 and subparagraphs including labor for subassemblies in the SPS-48E appendix A under Cat 1. S/N: 48P-04

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-48 Pedestal in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1, 3.6.6 and subparagraphs including labor for subassemblies in the SPS-48E appendix A under Cat 1. S/N: 48P-04 (D39).

SUBCLIN 0009AA

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N's: 49A-06, 49A-07, and 49A-08

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for

the AN/SPS-49 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N's: 49A-06 (F-20), 49A-07 (CR001), and 49A-08 (K0).

SUBCLIN 0009AB

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N's: 49A-09

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N's: 49A-09 (K-15).

SUBCLIN 0010AA

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Pedestal and wiring harness in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N's: 49P-06, 49P-08, and 49P-09

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Pedestal and wiring harness in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N's: 49P-06 (B-8), 49P-08 (G1), and 49P-09 (E-21).

SUBCLIN 0010AB

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Pedestal and wiring harness in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and



subparagraphs. S/N: 49P-10

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN assets for the AN/SPS-49 Pedestal and wiring harness in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.7 and subparagraphs. S/N: 49P-10 (P-25).

CLIN 0011

The CLIN extended description has changed from:

Replacement of all mandatory parts and execution of the overhaul procedures for USN and FMS assets for the AN/SPS-67(V)1 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.9 and subparagraphs. S/N: 67S-05 and 67S-06

To:

Replacement of all mandatory parts and execution of the overhaul procedures for USN and FMS assets for the AN/SPS-67(V)1 Antenna in accordance with attached Appendices, Supplements and Procedures and Statement of Work paragraphs 3.6.4.1 and 3.6.9 and subparagraphs. S/N: 67S-05 (180) and 67S-06 (J25).

CLIN 0035

The unit of issue has changed from Lot to Each.

CLIN 0013 is added as follows:

<u>ITEM NO</u>	<u>SUPPLIES/SERVICES</u>	<u>QTY</u>	<u>U/I</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
0013	Category 2 Repair SPS-48 Antenna  Authorization to proceed with repair is being provided to the contractor via execution of this modification. The price of (b)(4) will be deducted from the credit balance under P00004 of the basic contract. The starting balance is (b)(4) and the remaining balance is (b)(4)  S/N 48A-04 (D39)  See Exhibit A  FSC/PSC: 5840 FOB: Destination FFP	1	Each		NSP

CLIN 0014 is added as follows:

<u>ITEM NO</u>	<u>SUPPLIES/SERVICES</u>	<u>QTY</u>	<u>U/I</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
0014	Category 2 Repair SPS-48 Pedestal  Authorization to proceed with repair is being provided to the contractor via execution of this modification. The price of (b)(4) will be deducted from the credit balance under P00004 of the basic contract. The starting balance is (b)(4) and the remaining balance is (b)(4)  S/N 48P-04 (D39)  See Exhibit B  FSC/PSC: 5840 FOB: Destination FFP	1	Each		NSP

CLIN 0019 is added as follows:

<u>ITEM NO</u>	<u>SUPPLIES/SERVICES</u>	<u>QTY</u>	<u>U/I</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
0019	Category 3 Repair SPS-48 Antenna  Authorization to proceed with repair is being provided to the contractor via execution of this modification. The price of (b)(4) will be deducted from the credit balance under P00004 of the basic contract. The starting balance is (b)(4) and the remaining balance is (b)(4)  S/N 48P-04 (D39)  See Exhibit A  FSC/PSC: 5840 FOB: Destination FFP	1	Each		NSP

CLIN 0020 is added as follows:

<u>ITEM NO</u>	<u>SUPPLIES/SERVICES</u>	<u>QTY</u>	<u>U/I</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
0020	Category 3 Repair SPS-48 Pedestal  Authorization to proceed with repair is being provided to the contractor via execution of this modification. The price of (b)(4) will be deducted from the credit balance under P00004 of the basic contract. The starting balance is (b)(4) and the remaining balance is (b)(4)  S/N 48P-04 (D39)  See Exhibit B  FSC/PSC: 5840 FOB: Destination FFP	1	Each		NSP

SECTION E - INSPECTION AND ACCEPTANCE

The following Acceptance/Inspection Schedule was added for CLIN 0013:  
INSPECT AT INSPECT BY ACCEPT AT  
Destination Government Destination

ACCEPT BY  
Government

The following Acceptance/Inspection Schedule was added for CLIN 0014:  
INSPECT AT INSPECT BY ACCEPT AT  
Destination Government Destination

ACCEPT BY  
Government

The following Acceptance/Inspection Schedule was added for CLIN 0019:  
INSPECT AT INSPECT BY ACCEPT AT  
Destination Government Destination

ACCEPT BY  
Government

The following Acceptance/Inspection Schedule was added for CLIN 0020:  
INSPECT AT INSPECT BY ACCEPT AT  
Destination Government Destination

ACCEPT BY  
Government

## SECTION F - DELIVERIES OR PERFORMANCE

The following Delivery Schedule item for SUBCLIN 0008AB has been changed from:

DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
18-APR-2018 S/N 48P-04	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164

To:

DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
29-MAY-2018 S/N 48P-04 (D39)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) ANTENNA SYSTEMS (N00164-14-D-GR34) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164

The following Delivery Schedule for CLIN 0013 has been added:

DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
03-AUG-2018 S/N 48A-04 (D39)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) ANTENNA SYSTEMS (N00164-14-D-GR34) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164

The following Delivery Schedule for CLIN 0014 has been added:

DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
29-MAY-2018 S/N 48P-04 (D39)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) ANTENNA SYSTEMS (N00164-14-D-GR34) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164

The following Delivery Schedule for CLIN 0019 has been added:

DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
03-AUG-2018 S/N 48A-04 (D39)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) ANTENNA SYSTEMS (N00164-14-D-GR34) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164

The following Delivery Schedule for CLIN 0020 has been added:

DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
---------------	----------	-----------------	------------------

29-MAY-2018 S/N 48P-04 (D39)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) ANTENNA SYSTEMS (N00164-14-D-GR34) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
---------------------------------	---	---	--------

The following have been modified:  
DELIVERY INFORMATION  
DELIVERY INFORMATION

CLIN	DELIVERY DATE	QUANTITY	SHIP TO ADDRESS	DODAAC / CAGE
0001	N/A	N/A	N/A	N/A
0001AA	17-NOV-2017 S/N 48A-03 (C32)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0001AB	25-JAN-2018 S/N 48A-04 (D39)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0002	N/A	N/A	N/A	N/A
0002AA	02-NOV-2017 S/N 48P-03 (C-25)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0002AB	10-JAN-2018 S/N 48P-04 (D39)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0003	N/A	N/A	N/A	N/A

0003AA	31-AUG-2017 S/N 49A-06 (F-20)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0003AA	21-SEP-2017 S/N 49A-07 (CR001)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0003AA	12-OCT-2017 S/N 49A-08 (K0)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0003AB	02-NOV-2017 S/N 49A-09 (K-15)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0004	N/A	N/A	N/A	N/A
0004AA	21-SEP-2017 S/N 49P-06 (B-8)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0004AA	01-NOV-2017 S/N 49P-08 (G1)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0004AA	22-NOV-2017 S/N 49P-09 (E-21)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0004AB	13-DEC-2017 S/N 49P-10 (P-25)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0005	26-SEP-2017 S/N 67S-05 (180)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0005	24-OCT-2017 S/N 67S-06 (J25)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0007	N/A	N/A	N/A	N/A
0007AA	14-MAY-2018 S/N 48A-03 (C32)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164

0007AB 27-AUG-2018 S/N 48A-03 (C32)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0007AC 03-AUG-2018 S/N 48A-04 (D39)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0007AD 16-NOV-2018 S/N 48A-04 (D39)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0008 N/A	N/A	N/A	N/A
0008AA 20-FEB-2018 S/N 48P-03 (C-25)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0009 N/A	N/A	N/A	N/A
0009AA 05-OCT-2017 S/N 49A-06 (F-20)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0009AA 26-OCT-2017 S/N 49A-07 (CR001)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0009AA 16-NOV-2017 S/N 49A-08 (K0)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0009AB 07-DEC-2017 S/N 49A-09 (K-15)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0010 N/A	N/A	N/A	N/A
0010AA 06-DEC-2017 S/N 49P-06 (B-8)	1	NAVAL SURFACE WARFARE CENTER CRANE DIV M/F: (b)(6) (BLDG 3168) BLDG 3168 300 HWY 361 CRANE IN 47522-5001 (b)(6) FOB: Destination	N00164
0010AA 16-JAN-2018 S/N 49P-08 (G1)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164



0010AA	06-FEB-2018 S/N 49P-09 (E-21)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0010AB	27-MAR-2018 S/N 49P-10 (P-25)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0011	13-NOV-2017 S/N 67S-05 (180)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0011	08-DEC-2017 S/N 67S-06 (J25)	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164
0035	16-NOV-2018	1	(SAME AS PREVIOUS LOCATION) FOB: Destination	N00164

#### SECTION J - LIST OF DOCUMENTS, EXHIBITS AND OTHER ATTACHMENTS

The Table of Contents has changed from:

##### Exhibit/Attachment Table of Contents

DOCUMENT TYPE	DESCRIPTION	PAGES	DATE
Attachment 1	Scheduled Government Furnished Property form	5	11-JUL-2017
Attachment 2	Delivery Schedule Information inclusive of induction dates	1	11-JUL-2017

to:

##### Exhibit/Attachment Table of Contents

DOCUMENT TYPE	DESCRIPTION	PAGES	DATE
Attachment 1	Scheduled Government Furnished Property form	5	13-MAR-2018
Attachment 2	Planned Induction Schedule	1	12-MAR-2018

The Table of Contents has added:

##### Exhibit/Attachment Table of Contents

DOCUMENT TYPE	DESCRIPTION	PAGES	DATE
Attachment 3	Request for Variance	3	22-JAN-2018

RFV Number TSE-001

(End of Summary of Changes)